

## Maintenance Service- Smart 451 ForTwo

Brake system: brake test carried out.

Parking brake checked.

Indicator lamps in the instrument cluster and interior lighting checked for correct function.

Power windows, rear window heating, seat heating, cigarette lighter and mirror setting checked for correct function.

Horn, headlamp flasher, hazard warning lamps and turn signal lamps checked for correct function.

Heating and ventilation: controls checked for correct function.

Windscreen wipers and windscreen washer system checked for correct function.

Seat belts and buckles checked for operation and external damage.

Replace combination filter.

Tyre sealant expiry date checked.

Battery fluid level checked, corrected.

Key with remote control: replace the battery.

Bodywork inspected for paintwork damage.

Windscreen: condition checked.

Exterior lighting checked for correct operation.

Brake system: brake fluid level checked and corrected.

Brake fluid: wet boiling point checked.

Windscreen washer system: washer fluid level checked, corrected.

Central locking: checked for correct function.

Soft-top: checked for correct function (cabrio only).

Headlamp adjustment checked and corrected.

Headlamps: range control checked.

Front axle: brake pad thickness checked, condition of brake discs checked.

Rear axle: brake lining thickness checked.

Complete wheels: checked for damage and cracks; tread depth measured.

Tyre pressure checked, corrected.

Engine: coolant level and antifreeze content checked, corrected.

Exhaust system: checked for damage and leaks, including the mountings.

Underbody panelling and underbody: condition checked.

Brake lines and hoses: condition checked.

Fuel lines: checked for condition and leaks.

Poly-V-belt checked for wear and damage.

Engine and transmission: checked for damage, leaks and mounting defects.

Engine: oil changed and oil filter replaced.

Front axle: joints checked for play; condition of rubber gaiters checked.

Tie rod and steering arm joints: checked for play; condition of rubber gaiters checked.

Service display in the instrument cluster reset.